

**Recall Quarterly Report****22V-253**

**Manufacturer Name :** Ford Motor Company  
**NHTSA Recall No. / MFR Recall No. :** 22V-253 /22S24  
**Recall Subject :** Steering Column Wiring Too Short  
**Owner Notification Beginning Date :** JUL 28, 2022  
**Owner Notification End Date:** JUL 28, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 25, 2023	2022-4	19,175	12,267	132	0
1	OCT 27, 2022	2022-3	19,175	11,166	150	0

This Document Last Updated : JAN 26, 2023

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.