



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

April 22, 2022

Ms. Anca Collinsworth  
Tiny Idahomes LLC  
315 S Kings Road  
Nampa, ID 83687

NEF-107MR  
22V-260

**Subject:** Coupler Improperly Welded

Dear Ms. Collinsworth:

This letter serves to acknowledge Tiny Idahomes LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

RUGGED MOUNTAIN CUSTOM RV/TRAVEL TRAILER/2021-2022

**Mfr's Report Date:** April 15, 2022

**NHTSA Campaign Number:** 22V-260

**Components:**

EQUIPMENT:RECREATIONAL VEHICLE/TRAILER  
TRAILER HITCHES

**Potential Number of Units Affected:** 15

**Problem Description:**

Tiny Idahomes LLC (Tiny Idahomes) is recalling certain 2021-2022 Rugged Mountain Custom RV Travel trailers. The coupler was improperly welded, which may cause the trailer to separate from the tow vehicle.

**Consequence:**

Trailer separation from a tow vehicle can increase the risk of a crash.

**Remedy:**

Tiny Idahomes will inspect and replace the coupler as necessary, free of charge. Owner notification letters are expected to be mailed in April 22, 2022. Owners may contact Tiny Idahomes' customer service at 1-208-468-0576.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

**Please ensure the following requirements are met:**

The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

**AMENDED 573 REQUIRED.**

An identification and description of the risk to motor vehicle safety reasonably related to the defect or noncompliance (49 CFR 573.6 (c)(5)). All filings should state an increased risk of either a crash, injury or fire.

**AMENDED 573 REQUIRED.**

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

**AMENDED 573 REQUIRED.**

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

**AMENDED 573 REQUIRED.**

**Please be reminded of the following requirements:**

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Tiny Idahomes LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink that reads "Alex Ansley". The signature is fluid and cursive, with a checkmark-like flourish at the end.

Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement