



IMPORTANT SAFETY RECALL

**AUTOCAR, LLC SAFETY RECALL ACX-2202
NHTSA RECALL NO. 22V262**

June 2022

TO: U.S. Distributors
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect which relates to motor vehicle safety exists in 908, 2019– 2021 model year Xpeditor (ACX) chassis. These chassis were manufactured between March 4, 2019, and November 12, 2020, with non-sequential serial numbers in the range of 229795 through 234843. accordingly, a recall to address this issue is being initiated effective June 14, 2022.

**MODELS
AFFECTED:** Autocar Xpeditor (ACX) MY 2019-2021

**COMPONENTS
AFFECTED:** The hazard lamps will not function with the ignition off.

**SAFETY
DEFECTS AND
POTENTIAL
RISKS:** Non-compliance as the hazard lighting is disabled with the ignition and increases the risk of property damage, personal injury, or a crash.

**REPAIR
REQUIRED:** The hazard lamp wiring will be repaired at no charge to the owner.

**REPAIR
AVAILABLE:** VIN profiles in the Autocar Warranty System will be updated to show the open recall on June 14, 2022, and a spreadsheet of the affected VINs will be available in the Warranty system.

REMINDER: It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at warranty@autocartruck.com.

Sincerely,

AUTOCAR, LLC

ACF 00002 Rev. 000