

U.S. Department of Transportation

# National Highway Traffic Safety Administration

April 28, 2022

Mr. Michael Lanciotti CEO & President Kibbi, LLC 52216 SR 15 Bristol, IN 46507

1200 New Jersey Avenue SE Washington, DC 20590

NEF-107MR 22V-268

**Subject:** Electrical Relay May Overheat and Cause Fire

Dear Mr. Lanciotti:

This letter serves to acknowledge Kibbi, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

#### Makes/Models/Model Years:

RENEGADE/VIENNA/2021 RENEGADE/VILLAGIO/2021

Mfr's Report Date: April 20, 2022

NHTSA Campaign Number: 22V-268

## **Components:**

ELECTRICAL SYSTEM: WIRING: RELAYS/SOLENOIDS

**Potential Number of Units Affected:** 148

### **Problem Description:**

Kibbi, LLC (Kibbi) is recalling certain 2021 Renegade RV Vienna and Villagio motorhomes equipped with Dayton/Snyder electrical relays. A stranded wire used in the connector may cause the relay to overheat.

## **Consequence:**

An overheated electrical relay increases the risk of a fire.

## Remedy:

Dealers will remove the electrical relay and reconnect wiring as necessary. Dealers will also add a warning label by the Firefly touch screen that states, "Don't use Range, Microwave or Air Conditioning unit unless the coach is powered by shore or Generator." All repairs will be performed free of charge. Owner notification letters are expected to be mailed on April 29, 2022. Owners may contact Kibbi's customer service at 1-574-966-0196.

#### Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



# Please ensure the following requirements are met:

The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

The total number of products potentially containing the defect or noncompliance (49 CFR 573.6 (c)(3)).

AMENDED 573 REQUIRED.

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the electric relay. If your company manufactured the component itself, then please state so in 573.

AMENDED 573 REQUIRED.

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims. Please provide the date in which Kibbi decided to file a recall with NHTSA.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.



Kibbi, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

