Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company

One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone: 888-548-8514

This notice applies to your vehicle, VIN:

Replace Brake Booster
NHTSA Recall ID: 22V315
MBUSA ID: 2022090006 & 2022090007
STOP DRIVE REMEDY



<u> իրուկիսի իրիսկային իկարևորվիվը, որնին</u>

- Remedy parts are now available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealership as soon as possible.
- . This repair will be provided FREE of charge.

March, 2023

Dear Mercedes-Benz Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year ("MY") 2006-2011 ML-Class and MY2006-2012 GL-Class and R-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the issue?



Moisture may accumulate and cause corrosion in the brake booster housing unit, which can result in reduced brake performance. In some cases of severe corrosion, a particularly strong or hard braking application may cause mechanical damage in the brake booster, which can result in brake failure. In this case, it would not be possible to decelerate the vehicle via the brake pedal. Reduced brake performance or brake failure can increase the risk of a crash or injury.

What will your Mercedes-Benz Dealership do?



Parts are available for all affected vehicles to repair the recall condition. An authorized Mercedes-Benz dealer will replace the brake booster, free of charge. While the repair time may be less than 3 hours, your dealer can provide you with a better estimate of the overall time for this work. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time. You will not be charged for other service or repairs unless so requested.

How do I schedule the brake booster replacement?

- Find your nearest authorized Mercedes-Benz dealership at mbusa.com/recall to schedule your recall repair.
- Please mention you are scheduling an appointment for Mercedes-Benz Recall Campaign 2022090006 or 2022090007.
- You may be asked for your VIN, which for your convenience is located at the top of this letter.



IMPORTANT SAFETY RECALL

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company

One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone: 888-548-8514

What are next steps after the brake booster is replaced?

Once the brake booster is replaced, the issue is resolved and no further action is required for this recall campaign.

Steps to take.



- Find your nearest authorized Mercedes-Benz dealership at mbusa.com/recall to schedule your recall repair if the
 vehicle is not at the original inspecting dealership.
- Please mention you are scheduling an appointment to replace the Brake Booster for Recall Campaign 2022090006 or 2022090007.
- You may be asked for your VIN, which for your convenience is located at the top of this letter.

What if I no longer own or drive the vehicle?

In the event you no longer own or drive this vehicle, please visit **mbusa.com/recalls** to update your information by submitting your VIN using our VIN recall lookup tool and filling out the "no longer own" section on the website. If possible, please provide any contact information of the current owner/driver so we can contact them.

Additional Information for Owners:

A VIN-based recall lookup tool is available at **mbusa.com/recalls**, which can be used to check whether a vehicle has been subject to a safety recall, or had the remedy performed. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealership.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

Should an authorized Mercedes-Benz dealership be unable to address your concerns please contact us at 1-888-548-8514. We are always happy to hear from you.

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, Pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.



IMPORTANT SAFETY RECALL

Mercedes-Benz USA, LLC

A Mercedes-Benz Group AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone: 888-548-8514

Reimbursement to Customers for Repairs Performed Prior to Recall

If you have already paid to have this recall condition corrected you may be eligible to receive reimbursement. Requests for reimbursement may include parts, labor, fees and taxes. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Mercedes-Benz dealer. The following documentation must be presented to your dealer for reimbursement.

Original or clear copy of all receipts, invoices and/or repair orders that show:

- The name and address of the person who paid for the repair.
- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- · What problem occurred, what repair was done, when it was done and who repaired it.
- The total cost of the repair expense that is being claimed.
- · Proof of payment of repair (copy of front and back of cancelled check, or copy of credit card receipt).
- · Reimbursement will be made by check from your dealer.

Please speak with your dealer concerning this matter. Thank you for your cooperation.

We apologize for any inconvenience this may have caused and look forward to taking care of this important safety recall immediately.

Sincerely, Mercedes-Benz USA

