



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 1, 2022

Ms. Tiffani Torgeson
Manager Compliance and Regulatory Affairs
Daimler Trucks North America, LLC
4747 N Channel Ave
Portland, OR 97217

NEF-107ES
22V-379

Subject: Incorrect Tire Pressure Monitoring Information

Dear Ms. Torgeson:

This letter serves to acknowledge Daimler Trucks North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
FCCC/XC CHASSIS/2017-2022

Mfr's Report Date: May 26, 2022

NHTSA Campaign Number: 22V-379

Components:
TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS

Potential Number of Units Affected: 2,549

Problem Description:

Daimler Trucks North America, LLC (DTNA) is recalling certain 2017-2022 FCCC XC Chassis vehicles. The tire pressure monitoring system (TPMS) may report incorrect information, such as temperature and pressure values, on the instrument cluster.

Consequence:

Incorrect TPMS information may not alert the driver of an actual low pressure or high temperature tire condition, which can increase the risk of a crash.

Remedy:

Dealers will update the TPMS software, free of charge. Owner notification letters are expected to be mailed July 25, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL935.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information with their dates of receipt.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Daimler Trucks North America, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement