

Original Publication Date: October 26, 2022

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

SAFETY RECALL 22TA06 (Interim Notice 22TB06)

****IMPORTANT UPDATE****

Certain 2023 Model Year bZ4X
DO NOT DRIVE – Potential Loss of Vehicle Control
NHTSA Recall No. 22V-444

- Toyota is completing the final preparations for the remedy launch. **At this time, we expect that the remedy will be announced on 11/02/2022.**
- All parts required will be pre-deployed to the dealership for all confirmed vehicles at their location.
- In addition to the remedy for 22TA06, Toyota will also be announcing some Service Campaigns for the 2023 bZ4X at the same time.
- The additional Service Campaigns will involve installing some additional labels on the vehicle, which will be distributed directly to your dealership, and performing software updates. Additional detail will be provided in the Dealer Letter for each Service Campaign when they are announced on 11/02/2022.
- The estimated total repair time for both the 22TA06 remedy and the additional Service Campaign's remedies is six hours. Technician certification requirements will be Expert Technician (Hybrid).
- To reduce owner's inconvenience, please make arrangements to perform the remedy for these additional Service Campaigns at the same time that you perform the remedy for 22TA06.
- Vehicle owners will receive an email on 11/02/2022 outlining the Service Campaigns and explaining our intention to remedy these Service Campaigns at the same time as we perform the remedy for 22TA06.

Thank you for your cooperation.
TOYOTA MOTOR SALES, U.S.A., INC.