Toyota Motor Sales, USA, Inc. 6565 Headquarters Drive Plano, TX 75024 (469) 292-4000

Original Publication Date: October 05, 2022

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

## SAFETY RECALL 22TA06 (Interim Notice 22TB06)

## \*\*IMPORTANT UPDATE\*\*

Certain 2023 Model Year bZ4X

DO NOT DRIVE – Potential Loss of Vehicle Control

NHTSA Recall No. 22V-444

- The investigation into this concern has been concluded and a remedy has been developed.
- The remedy will involve replacing the wheels with improved ones and replacing the hub bolts with newly designed hub bolts with washers.
- A new Owner's Manual will also be provided with user information for the new hub bolts.
- Toyota is diligently working to prepare the parts needed to implement this remedy.
- The current estimate for remedy launch is Late October 2022 Early November 2022.

Thank you for your cooperation. TOYOTA MOTOR SALES, U.S.A., INC.