

August 2022

IMPORTANT SAFETY RECALL

AUTOCAR, LLC ACX-2204 DC-2202 ACTT-2201 NHTSA RECALL NO. 22V475

TO: U.S. Distributors

Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect which relates to motor vehicle safety exists in 653, 2022 – 2023 model year Xpeditor (ACX), Xspotter (ACTT) and Legend (DC) chassis. These ACX chassis were manufactured between May 14, 2021, and April 27, 2022, with non-sequential serial numbers in the range of 235460 through 241740. The ACTT chassis were manufactured between May 28, 2021, and April 26, 2022, with non-sequential serial numbers in the range of 235797 through 241736. The DC chassis were manufactured between May 13, 2021, and April 27, 2022, with non-sequential serial numbers in the range of 236158 through 241738. Accordingly, a recall to address this issue is being initiated effective August 30, 2022.

MODELS AFFECTED:	Autocar Xpeditor (ACX), Legend (DC) and Xspotter (ACTT) MY 2022-2023
COMPONENTS AFFECTED:	The steering gear may have been manufactured with fewer than required recirculating balls external fuse box may short circuit due to water intrusion.
<u>SAFETY</u> <u>DEFECTS AND</u> <u>POTENTIAL</u> <u>RISKS:</u>	A steering gear with fewer than the required number of recirculating balls may bind when loads are applied. In some cases, the balls may align on the same side of the gear's worm-shaft and concentrated loads may cause the gear's internal parts to fracture resulting in loss of vehicle steering. Loss of steering increases the likelihood of a crash.
<u>REPAIR</u> REQUIRED:	The steering gear will be inspected and or replaced at no charge.
<u>REPAIR</u> AVAILABLE:	VIN profiles in the Autocar Warranty System will be updated to show the open recall on August 30, 2022, and a spreadsheet of the affected VINs will be available in the Warranty system.
<u>REMINDER:</u>	It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.
	If you have any questions or concerns, please contact the Autocar Warranty Department at warranty@autocartruck.com.
Sincerely, AUTOCAR. LLC	

ACF 00002 Rev. 000