



**RECREATIONAL
VEHICLES**

985 North 900 West
Shipshewana, IN 46565

IMPORTANT SAFETY RECALL

KZ RV, L.P.

NHTSA Recall Number 22V-552

Transport Canada Recall Number 2022-411

Internal Recall Number: KZ-2022-04

Date: August 10, 2022

TO: KZ RV Dealer

Problem

The vehicles subject to this recall were built with a Lippert awning that has a bad plastic weld. As a result, the awning could rip which will result in the awning becoming detached from the coach resulting in personal injury, property damage, or a crash.

RANGE OF VEHICLES INVOLVED:

- 2022 & 2023 Connect, Confluence, Durango, Durango Gold, Sonic, Sportsmen, Sportsmen Classic, Sportsmen Sportster, SportTrek, Spree Escape, and Venom models.

WARRANTY REIMBURSEMENT:

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is 0.20 hours to inspect, 0.30 hours to repair, or 1.5 hours to replace.

SERVICE ACTION:

Follow the repair instructions provided by Lippert Components. These can be found at <https://support.lci1.com/awning-inspection-and-weld/seam-repair-22e-055>

encl. – Owners Letter

Delbert Miller

Vice President Corporate