
Important Safety Recall I-19-02 UPDATE Thursday, September 01, 2022 5:00:05 PM

External Email Think Before You Click.

Trouble viewing this email? Open it in your browser >



IMPORTANT SAFETY RECALL UPDATE

Steve,

In cooperation with the National Traffic and Motor Vehicle Safety Act, Polaris is conducting a voluntary recall of certain models:

Our records indicate that you are the owner of an **Test** with VIN **Test** affected by Safety Recall **Test**.

Indian Motorcycle has determined that all model year 2014-2020 (111 c.i.) motorcycles may experience loss of forward lighting. If this event does occur, the High Beam indicator will flash on the gauge cluster. If the motorcycle lighting malfunctions while in operation, it may reduce visibility and increase the risk of a crash.

To resolve this concern, Indian Motorcycle has developed a repair procedure to inspect the electrical connector for damage and replace the VCM if needed.

This recall was originally released in 2019. Based on ongoing investigation, Indian Motorcycle expanded the population of affected vehicles originally communicated

under Safety Recall I-19-02. The VIN associated with this email is now affected by Safety Recall I-19-02 and will need to be repaired by an authorized Indian Motorcycle dealer.

Owner Next Steps:

- Visit our <u>Product Safety Recall</u> web page to verify if your motorcycle is impacted by this safety recall. Search for the model or vehicle identification number (VIN) on the site to confirm.
- Schedule an appointment with an authorized Indian Motorcycle dealer. Do not attempt repairs yourself. Repairs must be done by an authorized Indian Motorcycle dealer. Your local dealer can be found on our <u>Dealer Locator</u> web page.
- Your Indian Motorcycle dealer is in the best position to answer your questions, but you may also contact our Owners Connections Department at **1-800-765-2747** to speak with a representative.

We apologize for this inconvenience and assure you that we are committed to customer satisfaction for riders to enjoy.

-Indian Motorcycle

Received This Notice In Error?

This notice was sent according to our most current registration information. If you no longer own this vehicle, contact your dealer to complete a transfer of ownership. Federal law requires that any vehicle lessor receiving this notice must forward a copy of this notice to the lessee within 10 working days after the day on which the notice is received.

This email was sent by Indian Motorcycle to steve.blanchette@polaris.com because you are a registered owner of a motorcycle affected by a recent safety recall notice. Please do not reply to this email. To contact us, please call us at 1-800-POLARIS or visit our <u>help page</u>.

> © 2022 Polaris Industries Inc. 2100 Highway 55, Medina, MN 55340, USA