

**From:**  
**To:**  
**Subject:** Safety Recall I-19-02 expanded VIN population  
**Date:** Monday, August 29, 2022 10:05:44 AM

**\*External Email\*** Think Before You Click.

Trouble viewing this email? [Open it in your browser >](#)



**Date:** August 29, 2022

**Attn:** All Dealership Personnel

**Subject:** Safety Recall I-19-02 expanded VIN population

**IMPORTANT SAFETY RECALL NOTICE**  
**Stop Sale**

**IMPORTANT STOP SALE NOTICE!**  
Stop selling and riding affected vehicles immediately.

**Safety Recall I-19-02**

---

Indian Motorcycle has determined that an electrical defect may exist in 2014-2020 Heavyweight Air Cooled Indian Motorcycles, resulting in the unexpected loss of forward lighting. This defect may also cause heat damage to the Vehicle Control Module (VCM) and

Pin 11 of the center VCM connector.

Indian Motorcycle has released this bulletin with instructions to inspect the VCM connector for damage, update the VCM software, and replace the VCM and pin 11 connector if damaged. Reference Unit Inquiry to verify affected VINs.

**Based on ongoing investigation, Polaris expanded the population of affected vehicles originally communicated under Safety Recall I-19-02. Motorcycles that have already had I-19-02 completed do not require any additional repairs.**

[View I-19-02 Safety Recall](#)

[View FAQ](#)

---

## What Dealers Should Do?

As of May 7, 2019, **YOU MUST NOT SELL OR DELIVER** any affected **NEW OR USED Model Year** 2014-2020 listed below until it is repaired according to the Safety Recall bulletin.

---

## Affected Units

**2014 - Chief Classic, Chief Vintage, Chieftain models**

**2015 - Chieftain, Chief Classic, Chief Vintage**

**2016 - Chieftain, Springfield, Chief Vintage**

**2017 - Chief Vintage, Chieftain, Chieftain Dark Horse, Chieftain Limited, Chieftain Elite, Springfield**

**2018 - Chief Vintage, Chieftain, Chieftain Classic, Chieftain Dark Horse, Chieftain Limited, Chieftain Elite, Springfield**

**2019 - Chief Vintage, Chieftain Classic, Springfield, Springfield Dark Horse**

**2020 - Chief Vintage, Springfield**

Check the Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units.

Please contact Indian Motorcycle Service by phone at 800-330-9407 or through Ask Polaris with any questions or concerns.

---

Thank you for your cooperation in this matter.

Sincerely,

*Indian Motorcycle Service*

