

Recall Quarterly Report

22V-653

Manufacturer Name : Roadtrek Inc.

NHTSA Recall No. / MFR Recall No. : 22V-653 / 2022-05

Recall Subject : Improperly Tightened Seat Mounting Bolts/FMVSS 207

Owner Notification Beginning Date : NOV 07, 2022

Owner Notification End Date: NOV 11, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	APR 27, 2023	2023-1	36	9	0	0
1	JAN 30, 2023	2022-4	36	5	0	0

This Document Last Updated : APR 27, 2023

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.