

September 8, 2022

Troy Niswonger Compliance Manager Jayco, Inc. 903 South Main Street Middlebury, IN 46540

Subject: Incorrectly Routed Refrigerator LP Gas Line

Dear Troy Niswonger:

This letter serves to acknowledge Jayco, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: JAYCO/WHITE HAWK/2022-2023

Mfr's Report Date: August 31, 2022

NHTSA Campaign Number: 22V-659

Components:

EQUIPMENT: APPLIANCE: REFRIGERATOR EQUIPMENT: RECREATIONAL VEHICLE/TRAILER: LPG SYSTEMS: LINES AND FITTINGS

Potential Number of Units Affected: 45

Problem Description:

Jayco, Inc. (Jayco) is recalling certain 2022-2023 White Hawk travel trailers. The refrigerator LP gas line may have been improperly routed and concealed in the underbelly of the trailer.

Consequence:

In the event of a gas leak, gas can build up inside the concealed area, increasing the risk of a fire.

Remedy:

Dealers will reroute the refrigerator LP gas line, free of charge. Owner notification letters are expected to be mailed September 30, 2022. Owners may contact Jayco customer service at 1-800-283-8267. Jayco's number for this recall is 9901579.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107KL 22V-659

Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Jayco, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alae Andry

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

