OMB Control No.: 2127-0004

Recall Quarterly Report

22V-694

Manufacturer Name: Forest River, Inc.

NHTSA Recall No. / MFR Recall No.: 22V-694 /210-1556 Recall Subject: LPG Quick Disconnect Improperly Tightened

Owner Notification Beginning Date : SEP 29, 2022

Owner Notification End Date: SEP 30, 2022



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 2 | JAN 17, 2023 | 2022-4 | 284 | 129 | 0 | 0 |
| 1 | OCT 12, 2022 | 2022-3 | 284 | 72 | 0 | 0 |

This Document Last Updated: JAN 19, 2023

Definitions:

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the $3^{\rm rd}$ quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.