## **Recall Quarterly Report**

22V-744

Manufacturer Name : Rivian Automotive, LLC NHTSA Recall No. / MFR Recall No. : 22V-744 /FSAM 997 Recall Subject : Steering Knuckle and Control Arm May Separate Owner Notification Beginning Date : NOV 11, 2022 Owner Notification End Date: NOV 11, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 27, 2023	2022-4	12,212	11,571	198	20

This Document Last Updated : JAN 30, 2023

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.