

Part 573 Safety Recall Report

22V-777

Manufacturer Name : HD Trailer MFG. LLC**Submission Date :** MAY 22, 2023**NHTSA Recall No. :** 22V-777**Manufacturer Recall No. :** Besser Axle**Manufacturer Information :**

Manufacturer Name : HD Trailer MFG. LLC

Address : 263 CR44050

POWDERLY TX 75473

Company phone : 4916759

Population :

Number of potentially involved : 15

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2022-2022 HD Trailer Non CDL Goosenecks

Vehicle Type : TRAILERS

Body Style : UNKNOWN

Power Train : NR

Descriptive Information : Besser Pro has let us know that they had a Recall on some of the 7000lb axles 78HF 54sc axle for defective welds on the spindle.

Production Dates : DEC 22, 2021 - JAN 28, 2022

VIN Range 1 : Begin : 7LKH3AP2XNP000759 End : 7LKH3AP2XNP000793 ☐ Not sequential**Description of Defect :**

Description of the Defect : Besser Pro had a Defective weld on 24 axles that we had purchased from them to use on our 7K non CDL gooseneck trailers.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The spindle has a risk to sheer off while driving down the road due to the defective weld.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : 7K Axles

Component Description : 7K Axles 78HF & 54SC

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Besser Pro

Address : 1500 30th St Nw
Paris Texas 75460

Country : United States

Chronology :

We were contacted by our Besser Pro sales rep on 07/23/2022 letting us know that they were having issues with their 7K axles due to a defective weld on the tube of the axle that connects to the spindle. This was the 7K 78HF 54SC axles. HD Trailer recall was October 2022

Description of Remedy :

Description of Remedy Program : HD Trailer is working with Besser Pro to replace all defective axles involved. At this point of the process, we have successfully replaced 90 percent of the axles.

How Remedy Component Differs from Recalled Component : Besser Pro has addressed the issue of the defective welds and has fixed this issue.

Identify How/When Recall Condition was Corrected in Production : Besser Pro reached out to HD Trailer about the defective axles, but HD Trailer wasn't aware of the recall until we were notified by email from NHTSA.

Recall Schedule :

Description of Recall Schedule : We have been working with the customers as well as Besser Pro to replace all defective axles.

Planned Dealer Notification Date : OCT 13, 2022 - OCT 31, 2022

Planned Owner Notification Date : OCT 31, 2022 - DEC 30, 2022

* NR - Not Reported