

# Recall Quarterly Report

## 22V-783

**Manufacturer Name :** Innovative Specialties LLC  
**NHTSA Recall No. / MFR Recall No. :** 22V-783 /  
**Recall Subject :** Deteriorating Rubber May Cause Axle Misalignment  
**Owner Notification Beginning Date :** DEC 13, 2022  
**Owner Notification End Date:** DEC 13, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JAN 30, 2023	2022-4	630	167	64	0

This Document Last Updated : JAN 30, 2023

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).  
**Recall Population :** The total number of products recalled by the manufacturer.  
**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.  
**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.  
**Total Removed :** Products that have been scrapped, stolen, or exported.