

Recall Quarterly Report**22V-787**

Manufacturer Name : Ford Motor Company
NHTSA Recall No. / MFR Recall No. : 22V-787 /22S66
Recall Subject : Fuel Pump Control Module Bracket Not Secured
Owner Notification Beginning Date : DEC 01, 2022
Owner Notification End Date: DEC 01, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	JUL 24, 2023	2023-2	26	24	0	0
2	APR 18, 2023	2023-1	26	20	0	0
1	JAN 24, 2023	2022-4	26	17	0	0

This Document Last Updated : AUG 01, 2023

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.