

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
FCCC Dealers – U.S. and Canada
Direct Warranty Customers – U.S. and Canada
Export Distributors

Daimler Truck North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090 800-547-0712
Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry on the Web using the [WSC Link on DTNAConnect](#)

REF #: ICI22-051
Effective: 12/21/22
Release: 12/21/22

SUBJECT: FL958 – Interim Recall Notice

This letter is to inform you that an interim recall notice is being sent to affected customers for recall *FL958 ~ Brake Modulator Valves*. The interim notices will be mailed on 12/23/2022. A copy (with French translation) follows for your reference.

This notice is for your information only. There is no action for customers or dealers to take. If customers inquire, please refer them to the interim notice.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the WSC Link on DTNAPortal.

REF #: ICI22-051
En vigueur: 21/12/22
Date de sortie: 21/12/22

OBJET: FL958 – Avis de rappel provisoire

Cette lettre a pour but de vous informer qu'un avis de rappel provisoire est envoyé aux clients concernés pour le rappel FL958 ~ Vannes modulatrices de freinage. Les avis provisoires seront postés 23/12/2022. Une copie (avec traduction française) suit pour votre référence.

Cet avis est pour votre information seulement. Les clients ou les revendeurs n'ont aucune action à entreprendre. Si les clients demandent, veuillez les renvoyer à l'avis intermédiaire.

Si vous avez des questions ou avez besoin de plus amples renseignements, communiquez avec le Service des campagnes de garantie en soumettant une demande via le lien WSC sur DTNAPortal.

The information contained in this letter supercedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.

IMPORTANT SAFETY RECALL

This notice applies to your vehicle(s), See enclosed VIN list

**December 2022
FL958
Interim Recall Notice
NHTSA #22V-817**

Subject: Brake Modulator Valves

This notice is sent to you in accordance with the requirements of the *National Traffic and Motor Vehicle Safety Act*.

Daimler Truck North America LLC (DTNA), on behalf of its Freightliner Trucks Division, and wholly owned subsidiary, Western Star Truck Sales, Inc., has decided that a defect which relates to motor vehicle safety exists on certain model years 2017-2023 Freightliner 114SD, Business Class M2, and Cascadia; and Western Star 47X, 49X, and 57X vehicles manufactured March 3, 2016, through June 18, 2022.

The single brake modulator valve may corrode, which during an Adaptive Cruise Control (ACC) braking event, could lead to a brake pull resulting in a sudden change in vehicle direction due to uneven braking on the front axle increasing the risk of a motor vehicle crash.

This is the first of two notices you will receive regarding this subject. This letter is to inform you of an upcoming Recall to correct the issue noted above. Daimler Truck is currently securing replacement parts. **There is no action for you to take at this time.**

The second notice will inform you when the final free remedy is available. **When you receive the second notice**, please contact your authorized Daimler Truck North America dealer to schedule the Recall for your vehicle.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimlertruck.com. For other concerns, you may contact the Customer Assistance Center at (800) 385-4357. If you are not able to have the defect remedied without charge and within a reasonable time, you may wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or go to <http://www.nhtsa.gov>.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT
Enclosure

**Daimler Truck
North America LLC**

Daimler Truck North America LLC
Warranty Campaigns Department
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone

**December 2022
FL958
Interim Recall Notice
Transport Canada #2022-626**

Subject: Brake Modulator Valves

This notice is sent to you in accordance with the requirements of the *Motor Vehicle Safety Act*. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

Daimler Truck North America LLC (DTNA), on behalf of its Freightliner Trucks Division, and wholly owned subsidiary, Western Star Truck Sales, Inc., has decided that a defect which relates to motor vehicle safety exists on specific model years 2017-2023 Freightliner 108SD, 114SD, Business Class M2, and Cascadia; and Western Star 47X, 48X, 49X, and 57X vehicles manufactured March 3, 2016, through June 18, 2022.

The single brake modulator valve may corrode, which during an Adaptive Cruise Control (ACC) braking event, could lead to a brake pull resulting in a sudden change in vehicle direction due to uneven braking on the front axle increasing the risk of a motor vehicle crash.

This is the first of two notices you will receive regarding this subject. This letter is to inform you of an upcoming Recall to correct the issue noted above. Daimler Truck is currently securing replacement parts. **There is no action for you to take at this time.**

The second notice will inform you when the final free remedy is available. **When you receive the second notice**, please contact your authorized Daimler Truck North America dealer to schedule the Recall for your vehicle.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days.

If you have questions about this Recall, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimlertruck.com. For other concerns, you may contact the Customer Assistance Center at (800) 385-4357. If you have a safety concern relating to this Recall, you may wish to contact Transport Canada – Motor Vehicle Safety at, 80 rue Noel, Gatineau, Quebec J8Z 0A1 or phone (800) 333-0510.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT
Enclosure

décembre 2022

FL958

**Avis provisoire de rappel
Transports Canada #2022-626**

Objet: Valves de modulateur de frein

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile*. La présente a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

Daimler Truck North America LLC (DTNA), au nom de sa Freightliner Trucks Division et de sa filiale à part entière, Western Star Truck Sales, Inc., a décidé qu'il existe un défaut relatif à la sécurité des véhicules automobiles pour les années de modèle spécifiques 2017-2023 Freightliner 108SD, 114SD, Business Class M2 et Cascadia; et les véhicules Western Star 47X, 48X, 49X et 57X fabriqués du 3 mars 2016 au 18 juin 2022.

La soupape du modulateur de frein unique peut se corroder, ce qui, lors d'un freinage avec le régulateur de vitesse adaptatif (ACC), pourrait entraîner une traction des freins, ce qui pourrait entraîner un changement soudain de direction du véhicule en raison d'un freinage inégal sur l'essieu avant, ce qui augmente le risque d'accident d'un véhicule à moteur.

Il s'agit du premier de deux avis que vous recevrez à ce sujet. La présente vise à vous informer d'un rappel à venir pour corriger le problème susmentionné. Daimler Truck sécurise actuellement les pièces de rechange. **Il n'y a aucune mesure à prendre pour le moment.**

Le deuxième avis vous informera lorsque le dernier recours gratuit sera disponible. **Lorsque vous recevez le deuxième avis**, veuillez communiquer avec votre concessionnaire autorisé Daimler Truck North America pour planifier le rappel de votre véhicule.

Si vous n'êtes pas propriétaire du véhicule qui correspond au (x) numéro (s) d'identification figurant sur l'avis de rappel, veuillez retourner l'avis au Service des campagnes de garantie avec tout renseignement que vous pouvez fournir nous aidera à trouver le propriétaire actuel. Si vous avez loué ce véhicule, la loi fédérale exige que vous transmettiez cet avis à : le locataire dans un délai de 10 jours. Si vous êtes un fabricant subséquent, la loi fédérale exige que vous transmettiez ce formulaire un avis à vos distributeurs et points de vente au détail dans un délai de cinq jours ouvrables.

Si vous avez des questions au sujet de ce rappel, veuillez communiquer avec le Service des campagnes de garantie au (800) 547-0712, de 7 h à 16 h, Pacific Time, Monday à Friday, adresse courriel DTNA.Warranty.Campaigns@Daimlertruck.com. Pour toute autre question, vous pouvez communiquer avec le Centre d'assistance à la clientèle au (800) 385-4357. Si vous avez des préoccupations en matière de sécurité relativement à ce rappel, vous pouvez communiquer avec Transports Canada — Sécurité des véhicules automobiles au 80, rue Noël, Gatineau (Québec) J8Z 0A1 ou téléphoner au (800) 333-0510.

Nous regrettons tout inconvénient que cette mesure pourrait causer, mais nous sommes certains que vous comprenez notre intérêt pour la sécurité des véhicules automobiles.

SERVICE DES CAMPAGNES DE GARANTIE
Enceinte