

## I-22-06 Safety Recall Update [DEX Alert](#) and [STOP Post](#)

### **DEX Alert**

**Group:** Alerts / Recall

**Start Date:** 4/13/2023

**Removal Date:** 7/13/2023

**Title:** Safety Recall I-22-06 update

#### **Alert Text:**

Additional information is now available for the I-22-06 Safety Recall - Chief and Scout Fuel Pump repair procedure. To ensure dealer technicians are aware of this information, an updated bulletin document and a new University of Polaris training is now required.

Click here: [I-22-06](#)

Click here: [FAQ](#)

### **STOP Post**

**Title:** Safety Recall I-22-06 Update

**Posting Date:** 4/13/2023

**Removal Date:** 7/13/2023

#### **Alert Text:**

Additional information is now available for the I-22-06 Safety Recall - Chief and Scout Fuel Pump repair procedure. To ensure dealer technicians are aware of this information, an updated bulletin document and a new University of Polaris training is now required.

To view the updated recall document: [CLICK HERE](#)

To view the updated FAQ: [CLICK HERE](#)