

I-22-06 Safety Recall **DEX Alert** and **STOP Post**

DEX Alert

Group: Alerts / Recall

Start Date: 11/22/2022

Removal Date: 2/22/2023

Title: Safety Recall I-22-06 Released

Alert Text:

Indian Motorcycle has determined that some Model Year 2022 Chief and Model Year 2021-2022 Scout motorcycles may experience a failure at the fuel pump during operation. If this occurs, the engine may stall increasing the risk of a crash and serious injury.

To address this concern, Indian Motorcycle has released this safety recall with instructions to replace the fuel pump with an improved part.

Click **HERE** to view Safety Recall I-22-06

Click **HERE** to view FAQ

STOP Post

Title: Safety Recall I-22-06 Released

Posting Date: 11/22/2022

Removal Date: 2/22/2023

Alert Text:

Indian Motorcycle has determined that some Model Year 2022 Chief and Model Year 2021-2022 Scout motorcycles may experience a failure at the fuel pump during operation. If this occurs, the engine may stall increasing the risk of a crash and serious injury.

 Click here: I-22-

06

Click here: FAQ