OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-856

Manufacturer Name: Shyft Group
Submission Date: APR 25, 2023
NHTSA Recall No.: 22V-856
Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Shyft Group

Address: 1541 Reynolds Road

Charlotte MI 48813

Company phone: 517-543-6400

Population:

Number of potentially involved: 153 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2023-2023 Utilimaster Walk-In Vans

Vehicle Type: LIGHT VEHICLES

Body Style: UNKNOWN

Power Train: GAS

Descriptive Information: The basis of this recall is related to a change in suppliers where the supplier built to

the part to print as opposed to an undocumented change request.

Production Dates: AUG 01, 2022 - OCT 10, 2022

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: The retaining nut that holds the shock mount together may not have proper

thread engagement and may be missing a tacked weld to hold the retaining nut in place. The retaining nut could come loose resulting in the bumper separating

from the vehicle.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: A bumper separating from the vehicle could result in the bumper becoming

unexpected road debris which could increase the risk of a crash.

Description of the Cause: During a supplier change, the new supplier built the parts to print which did

not call out the weld.

Identification of Any Warning Retaining nuts might separate without warning. A

that can Occur:

Involved	Components	:
----------	------------	---

Component Name 1 : NR
Component Description : NR
Component Part Number : NR

Supplier Identification:

Component Manufacturer

Name: NR Address: NR NR

Country: NR

Chronology:

On or near, 11/8 an issue was identified where the tack welds were not applied. On this day, Shyft evaluated the issued and determined a safety related issue might exists in the affected product. As it turns out, most of the product was contained, if not all. Warranting only the filing of this notice.

Description of Remedy:

Description of Remedy Program: NR
How Remedy Component Differs NR
from Recalled Component:

Identify How/When Recall Condition NR
was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

^{*} NR - Not Reported