VOLKSWAGEN DEALER COMMUNICATION

Advance Notice - Safety Recall 69EH / Passenger Frontal Airbag (Folding)

This notice is for:	 ✓ Dealer P ✓ General ✓ Sales Ma 	Manager	✓ Parts	ce Manager Manager ce Consultant	✓ Warranty A✓ Technicians	dministrator S	
Date:	November 22, 2022						
Issue:	On certain vehicles, the passenger frontal airbag may not have been folded properly. As a result, the airbag may not inflate properly in a crash. An airbag that does not inflate properly could create an increased risk of injury in a crash.						
Precautions	Volkswagen recommends avoiding use of the front passenger seat whenever possible until the recall work has been performed.						
Repair:	 REPAIR NOT YET AVAILABLE Check daily campaign open inventory report or OMD for affected vehicles in inventory. 						
Affected Vehicles	Country	Beginning Model Year	Ending Model Year	Ve	hicle	Vehicle Count	
	USA	2021	2021	I	D4	55	
	CAN	2021	2021	I	D4	30	
Notes:							
	<u>New Vehicles in Dealer Inventory:</u> It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.						
	<u>Pre-Owned Vehicles in Dealer Inventory:</u> Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.						

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.