

# Part 573 Safety Recall Report

## 22V-894

**Manufacturer Name :** OLD SCHOOL TRAILERS, LLC**Submission Date :** DEC 05, 2022**NHTSA Recall No. :** 22V-894**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : OLD SCHOOL TRAILERS, LLC

Address : 1933 EISENHOWER DR. N  
GOSHEN IN 46526

Company phone : 574-596-4828

**Population :**

Number of potentially involved : 16

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2022-2022 Old School Trailer Old School Trailer

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Old School Trailers, used the shipment information provided by Lippert and determined the units that we used the awning in. Products not included in the recall do not have the suspect awnings installed.  
16 Old School Trailers.

Production Dates : APR 06, 2022 - MAY 10, 2022

VIN Range 1 : Begin : 7LABT2214NG000187 End : 7LABT2217NG000202

☐ Not sequential**Description of Defect :**

Description of the Defect : Per Lippert description, there may be an issue with the weld on the awnings supplied by Lippert

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In extreme cases, the fabric could detach from the awning rail and remain attached to the awning frame. This could allow the awning to drop and extend beyond normal operation.

Description of the Cause : NR

Identification of Any Warning : A visible warning would include seeing a partial weld separate the end of the that can Occur : awning roll along the coach

**Involved Components :**

Component Name 1 : Lippert Awning

Component Description : Awning

Component Part Number : V000256341

### Supplier Identification :

#### Component Manufacturer

Name : Lippert

Address : 3501 Count Road 6 East  
Elkhart Indiana 46514

Country : United States

### Chronology :

July 20, 2022

### Description of Remedy :

Description of Remedy Program : I will notify the dealers and customers of this recall and provide the instructions provided by Lippert.  
The dealers will file their claims directly with Lippert.

How Remedy Component Differs from Recalled Component : The remedy component is certified by Lippert not to have any issues.

Identify How/When Recall Condition was Corrected in Production : All shipments received from Lippert after 6/16/22 were built using their improved processes.

### Recall Schedule :

Description of Recall Schedule : I will be creating a letter to mail to the dealer and I will create a letter that will go to the retail owner.

Planned Dealer Notification Date : DEC 12, 2022 - DEC 19, 2022

Planned Owner Notification Date : DEC 05, 2022 - DEC 19, 2022

\* NR - Not Reported