



Recall Alerts

To: Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Region: U.S.
 CAN

Bulletin: SRA-V22-05
Date: December 9, 2022
Valid to: N/A
Action Required? Yes No

From: Gerard Hones, Regulatory Specialist Government Reporting
Subject: Safety Recall RVXX2205, Air Tank Bracket

Description of Defect:

On certain vehicles, air tank bracket hardware was over torqued resulting in fastener failure. This may result in air tanks dragging on the roadway. Air tank may detach from the vehicle and result in road debris, which may result in a vehicle crash.

Volvo will replace fasteners which may have been over-torqued.

Models/ Model Years Affected:

Certain 2022 and 2023 Volvo VNL model vehicles manufactured from June 1, 2021 through October 17, 2022.

Vehicle Quantities:

Volvo 412 (all US)

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle list will be posted on the Trucks Dealer Portal December 9, 2022.
- Owner notification letters will be released on or before December 21, 2022.

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.