

Recall Quarterly Report**22V-942**

Manufacturer Name : BMW of North America, LLC
NHTSA Recall No. / MFR Recall No. : 22V-942 /
Recall Subject : Driver's Seat Backrest Missing a Bolt
Owner Notification Beginning Date : DEC 23, 2022
Owner Notification End Date: FEB 17, 2023



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2 | APR 28, 2023 | 2023-1 | 4 | 3 | 0 | 0 |
| 1 | JAN 26, 2023 | 2022-4 | 4 | 1 | 0 | 0 |

This Document Last Updated : MAY 03, 2023

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.