



**Date:** February 2, 2023

**Attn:** All Dealership Personnel

**Subject:** Safety Recall I-23-01 Released

## **IMPORTANT SAFETY RECALL NOTICE**

### **Stop Sale**

**IMPORTANT STOP SALE NOTICE!**  
Stop selling affected vehicles immediately.

### **Safety Recall I-23-01**

Indian Motorcycle has determined that on Model Year 2022 Chief, Chief Bobber, Chief Bobber Darkhorse, Chief Darkhorse, Super Chief, and Super Chief Limited motorcycles there is a potential for the sidestand to not fold rearward and upward if it contacts the ground when the motorcycle is moving forward, increasing the risk of a crash or serious injury.

To address this concern, Indian Motorcycle has released this safety recall with instructions to replace the sidestand with an improved part.

[View I-23-01 Safety Recall](#)

[View I-23-01 FAQ](#)

### **What Dealers Should Do?**

As of January 05, 2023, **YOU MUST NOT SELL OR DELIVER** any affected **NEW OR USED** Model Year 2022 Chief, Chief Bobber, Chief Bobber Darkhorse, Chief Darkhorse, Super Chief, and Super Chief Limited affected by this Stop Sale until it is repaired according to the Safety Recall.

## Affected Units

**2022 Chief, Chief Bobber, Chief Bobber Darkhorse, Chief Darkhorse, Super Chief, and Super Chief Limited**

Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected units.

Please contact Indian Motorcycle Service by phone at 800-330-9407 or through Ask Polaris with any questions or concerns.

---

Thank you for your cooperation in this matter.

Sincerely,

*Indian Motorcycle Service*

© 2023 Polaris Industries Inc.  
2100 Highway 55, Medina, MN 55340, USA