## **Product Safety Recall**

Due to quality concerns recently brought to our attention, Platinum Driveline is issuing a recall to the ensure safety of our customers.

The concern is that the pressure plates listed below may have been manufactured using incorrect materials. These parts require ductile metal, but a grey-iron material may have been used by our vendor. There is a serious possibility that the covers may fail under some conditions.

Platinum Driveline takes product quality concerns extremely seriously, so although the issue may not be present in all units, we will be recalling all items listed below sold from: **01/17/2023 to 09/27/2023.** 

## **Affected Items:**

• 361986

## Kits that may contain Affected Items

- 07-181 (featuring build reference numbers listed below)
  - 0 12450
  - 0 12657
  - 0 13514

We acknowledge the financial implications of conducting a product recall. We are conducting a thorough investigation in accordance with our ISO Quality Management System to implement improvements to our product approval procedures and ensure that all newly sourced products exceed industry standards.

Thank you for your continued support. For any questions, please contact us via email or by phone as listed below.