



## IMPORTANT SAFETY RECALL

**AUTOCAR, LLC ACX-2303 ACMD-2301 ACTT-2301**

**NHTSA RECALL NO. 23V023  
March 2023**

**TO:** U.S. Distributors  
Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Autocar, LLC has determined that a defect which relates to motor vehicle safety exists in 11353, 2008 - 2020 model year WXLL, WX, ACX (Xpeditor), ACTT (Xspotter) and ACMD (Xpert) chassis. The WXLL chassis were manufactured between March 12, 2007, and June 5, 2009, with non-sequential serial numbers in the range of 205511 and 209868. The WX chassis were manufactured between February 6, 2007, and October 30, 2009, with non-sequential serial numbers in the range of 205422 through 210109. The ACX chassis were manufactured between November 30, 2007, and March 10, 2020, with non-sequential serial numbers in the range of 206686 through 233162. The ACTT chassis were manufactured between January 12, 2009, and January 20, 2020, with non-sequential serial numbers in the range of 208644 through 232396. The ACMD chassis were manufactured between January 19, 2013, and February 8, 2016, with non-sequential serial numbers in the range of 215560 through 222135. Accordingly, a recall to address this issue is being initiated effective March 24, 2023

**MODELS** Autocar Xpeditor (ACX, WX, WXLL) 2008-2020, Xspotter (ACTT) MY 2010-2020 and  
**AFFECTED:** Xpert (ACMD) MY 2012-2016.

**COMPONENTS** The parking brake valve vent line.  
**AFFECTED:**

**SAFETY** A worn park brake control valve (PP1) can develop an internal leak and pass air  
**DEFECTS AND** through the exhaust port after the park brake is applied. Under specific conditions,  
**POTENTIAL** the internal leak combined with vent line plumbing may result in accumulated back  
**RISKS:** pressure sufficient to allow the park brakes to release, increasing the risk of a crash.

**REPAIR** The parking brake control valve vent line will be removed at no charge.  
**REQUIRED:**

**REPAIR** VIN profiles in the Autocar Warranty System will be updated to show the open recall on  
**AVAILABLE:** March 24, 2023 and a spreadsheet of the affected VINs will be available in the Warranty system.

**REMINDER:** It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at [warranty@autocartruck.com](mailto:warranty@autocartruck.com).

Sincerely,  
**AUTOCAR, LLC**

ACF 00002 Rev. 000