

Recall Quarterly Report

23V-055

Manufacturer Name : Newell Coach Corp.
NHTSA Recall No. / MFR Recall No. : 23V-055 /
Recall Subject : Battery Disconnect Switch May Fail
Owner Notification Beginning Date : FEB 13, 2023
Owner Notification End Date: FEB 13, 2023



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
3	OCT 10, 2023	2023-3	13	5	0	3
2	JUL 17, 2023	2023-2	13	4	0	3
1	APR 11, 2023	2023-1	13	2	0	3

This Document Last Updated : OCT 11, 2023

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.