



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

February 10, 2023

Mr. Mike Becker  
Director of Corporate Compliance  
Forest River, Inc.  
2324 Century Drive  
Goshen, IN 46528

NEF-107KL  
23V-061

**Subject:** Cooktop Gas Valves May Fracture Causing Gas Leak

Dear Mr. Becker:

This letter serves to acknowledge Forest River, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

COACHMEN/BEYOND/2023  
COACHMEN/GALLERIA/2022-2023  
COACHMEN/NOVA/2023

**Mfr's Report Date:** February 9, 2023

**NHTSA Campaign Number:** 23V-061

**Components:**

EQUIPMENT:APPLIANCE:OVEN/STOVE/COOKTOP

**Potential Number of Units Affected:** 12

**Problem Description:**

Forest River, Inc. (Forest River) is recalling certain 2022-2023 Coachmen Galleria, 2023 Coachmen Beyond, and 2023 Nova motorhomes, equipped with SDS2 2-Burner Drop-in Cooktops with part numbers 3031AST and 3032AST. The internal aluminum burner tubes that connect to the gas valves may fracture and cause a gas leak.

**Consequence:**

A gas leak in the presence of an ignition source can increase the risk of a fire.

**Remedy:**

Dealers will install a regulator support bracket, free of charge. Owner notification letters are expected to be mailed March 21, 2023. Owners may contact Forest River Customer Service at 1-574-825-6307. Forest River's number for this recall is 225-1601.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Forest River, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at [kristin.lepper@dot.gov](mailto:kristin.lepper@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement