News Channel Update

Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Department Manager, Vehicle
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services
RE: Recall Campaign Initial Notification	
Check Front Axle Wiring Harness	DATE: February 24, 2023
MY19-22 G-Class (463 platform)	

IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

Gregory Gunther

Department Manager, Vehicle Compliance & Analysis



Recall Campaign Initial Notification			February 24, 2023	
Campaign No. :	NHTSA ID	Campaign Desc. :	Check Front Ayle Wiring Harness	
ТВА	23V097	23P5491809	Check Front Axle Wiring Harness	
	recall campaign will b		ng harness on <u>26,116</u> Model Year ("MY") 2019-2022 G-Class (463 ov website and may generate questions from customers. Affected NG" on February 24, 2023.	
		Backgrou		
Issue on certain Model Ye harness might contain harness over time. A could potentially incompany through an indicator		on certain Model Year ("MY") harness might contact an aux harness over time. As a result, could potentially increase the through an indicator lamp or v	Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that Model Year ("MY") 2019-2022 G-Class (463 platform) vehicles, the front axle wiring ght contact an auxiliary oil cooler and chafe. This could potentially damage the wiring er time. As a result, impairment of ABS and ESP functionality cannot be ruled out, which atially increase the risk of a crash. If the failure occurs, the driver would be made aware indicator lamp or warning message in the instrument cluster.	
What We're Doing		MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealership will inspect the front axle wiring harness on the affected vehicles and replace it, if necessary. After inspection if the wiring harness is not replaced a protective sleeve will be installed,		
Parts		Remedy is not available at t		
		Vehicles Aff	ected	
Vehicle Model Year(s)		2019-2022		
Vehicle Model		G-Class		
		Vehicle Popu	lations	
Total Recall Population	Total Recall Population 26,116			
Total Vehicles in Dealer Inventory 7		7		
notification until th Instructio Loaner and demonstra pro	e vehicle has been ns will be available ator vehicles may c ocess, please check	repaired. Once the remedy is in Star TekInfo. Once the rep- ontinue to be driven, but mus c for other repair measures w	rlease any new vehicles in dealer inventory covered by this available, the vehicles will be flagged as "OPEN" and Work air is complete the vehicle may be sold or leased. It not be retailed until repaired. As a matter of normal service hich might be applicable to the vehicle(s). ar rental companies to rent new vehicles covered by this has been repaired.	
Next Steps/Notes				
Customer Notification	Timeline	Customer letters will be ma	illed on or before April 14, 2023.	
AOMS/SOMS		AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.		
Rental Fleet Partners	_		les in your fleet. Please contact your respective MBUSA fleet formation and next steps. For repairs, please contact your	
			maintain a high level of vehicle quality and customer satisfaction. ssistance Center at 1-800-FOR-MERCEDES.	

