## **IMPORTANT SAFETY RECALL INFORMATION**

Issued in Accordance With Federal Law



## URGENT SAFETY RECALL NOTICE

Your 2021 DODGE DURANGO SXT RWD is under recall for Rear Spoiler.

To schedule your recall repair contact your dealership or the FCA US Recall Team at 1-800-853-1403.



Visit <u>recalls.mopar.com</u> for more information or call the FCA US Recall Team at 1-800-853-1403

## **Details of the Recall**

The rear spoiler on your vehicle may be over-flush to the roof, allowing contact to the roof when cycling the liftgate. Vehicle occupants may hear the spoiler hitting the body when opening or closing the liftgate, or a rattle from the spoiler being loose while driving. An over-flush rear spoiler may become damaged when cycling the liftgate which may result in the spoiler becoming partially detached from the vehicle. Rear spoilers that become partially detached may separate from the vehicle while driving, potentially creating a road hazard to operators and occupants of other vehicles, and can cause such vehicles to crash without prior warning.

FCA US will repair your vehicle free of charge (parts and labor). To do this, your dealer will inspect and, if necessary, replace the rear spoiler. The estimated repair time is 1 hour. In addition, your dealer will require your vehicle for proper check-in, preparation, and check-out during your visit, which may require more time. Your time is important to us, so we recommend that you schedule a service appointment to minimize your inconvenience.

♦ Simply contact your Chrysler, Jeep®, Dodge or RAM dealer right away to schedule a service appointment.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations FCA US LLC Team 1-800-853-1403 recalls.mopar.com