## IMPORTANT SAFETY RECALL



DEPARTMENT OF COMPLIANCE VEHICLE SAFETY AND RECALL MANAGEMENT BUILDING 11 423 N MAIN ST MIDDLEBURY, INDIANA 46540-9218

NHTSA RECALL: 23V133 CANADA RECALL: 2023-103 FR ID: 310-1603

Integrity

Safety

Quality

o Customer Service

<<VIN>>

<<OWNER NAME/DEALERNAME>>

<<ADDRESS>>

<<CITY>>, <<ST>> <<ZIP-XXX>>

March 2023

This Notice applies to your vehicle VIN listed above.

#### Dear Forest River Customer:

This notice is sent to you in accordance with the requirements *Motor Vehicle Safety Act*. This notice is also sent in accordance with the requirements of the United States' *National Traffic and Motor Vehicle Safety Act*. Forest River has decided that a defect, which relates to the motor vehicle safety, exists in one single 2013 Coachmen Cross Country, in addition to certain 2023 Coachmen Sportscoach Class A Motorhome recreational vehicles. This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

## WHAT IS THE DEFECT/NONCOMPLIANCE?

According to the Recall Notice - 23E008 - received from Lippert Components: "The defect is an attachment point within the entry door latch supplied to Lippert for installation into specific series of RV Entry Doors. A specific attachment point was inadvertently weakened when the vendor implemented an improvement to create a more secure attachment groove for the retaining ring in the handle design of the latch."

## EVALUATION OF THE RISK TO THE VEHICLE AND OPERATOR(S) RELATED TO THE RECALL.

According to the Recall Notice - 23E008 - received from Lippert Components: "A defective entry door latch would not allow entry or exit via the door." Increasing the risk of injury.

#### WHAT IS FOREST RIVER AND OUR DEALERSHIPS GOING TO DO?

Forest River is notifying dealerships of the recall. You may have the recall corrected at any Forest River dealership. However, it is preferable if you have your selling dealership perform the remedy. Forest River completely covers your cost for the remedy; you will not receive any bill of sale for anything covered under the above recall number.

#### WHAT SHOULD YOU DO?

Please contact your dealer immediately and request a service appointment to schedule the free remedy. The entry door lock will be inspected and replaced if necessary. The vehicle Owner is responsible for arranging to have the work completed. Please state you have been notified by Forest River of having a recall in process for your vehicle and provide the recall number for the dealership. It is also helpful to the dealership to have a copy of this letter when you take your vehicle in for the recall remedy.

You may also visit www.forestriverinc.com for dealer locations.

#### **HOW LONG WILL THE REMEDY PROCESS TAKE?**

The estimated time of repair is .7 hours. However, the dealership may need to keep your vehicle or schedule an appointment with you for a later date to fit into their regular service schedule.

### WHAT IF YOU HAVE PREVIOUSLY PAID FOR REPAIRS TO YOUR VEHICLE FOR THIS PARTICULAR CONDITION?

If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized .Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:

Sportscoach Forest River, Inc Attn: Warranty Manager PO Box 30 Middlebury, IN 46540

# IMPORTANT SAFETY RECALL

## WHAT IF YOU NO LONGER OWN THIS VEHICLE?

If you no longer own this vehicle and have the address for the current owner, please forward this letter to the new owner within 10 working days after the day in which the notice is received. You have received this letter because government regulations require that a notification is sent to the last known owner of record. Our records indicate that you are the current owner.

PLEASE NOTE: FEDERAL LAW REQUIRES THAT ANY VEHICLE LESSOR RECEIVING THIS RECALL NOTICE MUST FORWARD A COPY OF THIS NOTICE TO THE LESSEE WITHIN TEN DAYS.

#### MAY FOREST RIVER ASSIST YOU FURTHER?

If you have difficulties getting your vehicle repaired, please contact your Forest River Representative listed below:

CONTACT	PHONE
SPORTSCOACH CUSTOMER SERVICE	(574) 825-8212
LIPPERT CUSTOMER SERVICE	(432) 547-7378

If you are still having difficulty getting your vehicle repaired in a reasonable amount of time or without charge, you may write to the following address:

#### For US Owners Please Contact:

Administrator National Highway Traffic Safety Administration 1200 New Jersey Ave, S.E. Washington, D.C. 20590

Or you may call the toll free Vehicle Safety Hotline at 1-888-327-4236 or (TTY: 1-800-424-9153).

Or visit www.safercar.gov and search; Recall ID: 23V133

#### **For Canadian Owners Please Contact:**

Head of Recalls Motor Vehicle Safety Investigations Laboratory Transport Canada 80 Noël street, Gatineau, Quebec, J8Z 0A1

Telephone (800) 333-0510 Facsimile (819) 420-4292

Recall ID: 2023-103

Sincerely, Forest River Inc. Office of Corporate Compliance