

Part 573 Safety Recall Report

23V-426

Manufacturer Name : Stoughton Trailers, LLC

Submission Date : JUN 14, 2023

NHTSA Recall No. : 23V-426

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Stoughton Trailers, LLC

Address : 416 South Academy Street

Stoughton WI 53589-0606

Company phone : 608-873-2500

Population :

Number of potentially involved : 1,152

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2023-2024 Stoughton Trailer Intermodal Container Chassis

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Population was determined by identifying when issue occurred to when the manufacturing plant stopped shipping suspect units to customer.
This is the only product built at this manufacturing plant.

Production Dates : MAR 08, 2023 - MAY 23, 2023

VIN Range 1 : Begin : 1DW4C5327PWB22345 **End :** 1DW4C5323RWB64532 Not sequential

Description of Defect :

Description of the Defect : Inadequate wheel lug nut torque

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Potential loss of wheel during transit

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Received report of wheel loss on 5-24-2023. Secured all units from shipping to customer 5-24-2023. Started investigation at manufacturing plant of potential cause with no evident root cause. An additional wheel off report was received 6-8-2023 with evidence of units with low wheel lug nut torque readings at the customers location which prompted additional investigations at their yards which resulted in additional units identified with low wheel lug nut torque.

Description of Remedy :

Description of Remedy Program : All wheel lug nuts will need to be checked for adequate torque values and corrected to proper value. All reimbursements submitted to Stoughton Trailers will be processed through our accounting department for reimbursement.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : 5-24-2023 A redundant torque inspection process was put in place in addition to torque process audits for final inspection of the wheel lug nut.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JUN 26, 2023 - JUN 27, 2023

* NR - Not Reported