



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 23, 2023

Mr. Chris Sandvig
Volkswagen Group of America, Inc.
3800 Hamlin Road
Auburn Hills, MI 48326

NEF-107DR
23V-437

Subject: Deformation of the Strut Mount

Dear Mr. Sandvig:

This letter serves to acknowledge Volkswagen Group of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:
VOLKSWAGEN/GOLF R/2023
VOLKSWAGEN/GTI/2023

Mfr's Report Date: June 21, 2023

NHTSA Campaign Number: 23V-437

Components:
SUSPENSION:FRONT:MACPHERSON STRUT

Potential Number of Units Affected: 59

Problem Description:

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2023 Golf R A8 and Golf GTI vehicles. The strut mount may be deformed, loosening the bolted connections to the suspension strut mounting.

Consequence:

Loose suspension connections can cause steering instability, increasing the risk of a crash.

Remedy:

Dealers will inspect and replace the right and/or left suspension strut mountings, as necessary, free of charge. Owner notification letters are expected to be mailed August 18, 2023. Owners may contact Volkswagen's customer service at 1-800-893-5298. Volkswagen's number for this recall is 40T3.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

We have received Volkswagen's proposed owner notification letter and it has been approved for distribution.



Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Volkswagen Group of America, Inc.'s contact for this recall will be Darishea Rollins who may be reached by email at darishea.rollins@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement