

Advance Notice – Safety Recall 28H7 / Ignition Switch

This notice is for:	 ✓ Dealer P ✓ General ✓ Sales Ma 	Manager	 ✓ Service Man ✓ Parts Manag ✓ Service Const 	er ✓ Technicia	Administrator ns
Date:	September 01, 2023				
Issue:	In vehicles equipped with a conventional ignition switch, the polyfuse can fail, particularly when the vehicle is operated in high temperature environments. If the polyfuse fails, it can result in the engine stalling while driving and failure of the vehicle's electrical system, increasing the risk of a crash.				
Repair:	 REPAIR NOT YET AVAILABLE Check daily campaign open inventory report or OMD for affected vehicles in inventory. Volkswagen is working to make a recall remedy available as soon as possible for the affected vehicles. Dealers and owners will be notified in writing once the recall remedy work can be performed. 				
Affected Vehicles	Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
	USA	2019	2020	JETTA	47,651
	CAN	2019	2020	JETTA	6,786
	*Counts reflect overall population; some vehicles may have already been repaired. Check Campaigns/Action: screen in Elsa <u>on the day of repair</u> to verify that a VIN qualifies for repair under this action. Elsa is the <u>only</u> valid campaign inquiry & verification source.				
Notes:	Notes: IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS				
	New Vehicles in Dealer Inventory: It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety. Pre-Owned Vehicles in Dealer Inventory: Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.				

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.