

U.S. Department of Transportation

# National Highway Traffic Safety Administration

October 6, 2023

Ms. Pascale Belanger Volvo Bus Corporation 260 Banker road Plattsburgh, NY 12901 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107DR 23V-668

Subject: Power Cables Not Properly Connected

Dear Ms. Belanger:

This letter serves to acknowledge Volvo Bus Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

### Makes/Models/Model Years:

VOLVO BUS/9700/2023

Mfr's Report Date: October 3, 2023

NHTSA Campaign Number: 23V-668

**Components:** 

**ELECTRICAL SYSTEM** 

Potential Number of Units Affected: 14

## **Problem Description:**

Volvo Bus Corporation (Volvo Bus) is recalling certain 2023 Volvo 9700 vehicles. The fasteners that secure the power cable connections may not have been tightened securely.

## **Consequence:**

Unsecured power cables can overheat, increasing the risk of a fire.

### Remedy:

Prevost will inspect and tighten the power cable fasteners, as necessary, free of charge. Owner notification letters are expected to be mailed November 23, 2023. Owners may contact Volvo Bus customer service at 1-866-870-2046. Volvo Bus' number for this recall is SR23-86.

#### **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Volvo Bus Corporation's contact for this recall will be Darishea Rollins who may be reached by email at darishea.rollins@dot.gov. We look forward to working with you.

Sincerely.

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Alex Anky

Enforcement

