

U.S. Department of Transportation

National Highway Traffic Safety Administration

October 10, 2023

Mr. Chris Sandvig Volkswagen Group of America, Inc. 3800 Hamlin Road Auburn Hills, MI 48326 1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107DR 23V-671

Subject: Side Air Bag May Deploy Improperly

Dear Mr. Sandvig:

This letter serves to acknowledge Volkswagen Group of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

VOLKSWAGEN/ATLAS/2019

Mfr's Report Date: October 4, 2023

NHTSA Campaign Number: 23V-671

Components:

AIR BAGS:SIDE/WINDOW:CURTAIN

Potential Number of Units Affected: 2

Problem Description:

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019 Atlas vehicles. The driver's side impact air bag may be missing a weld at the side air bag housing.

Consequence:

The driver's side impact air bag could deploy improperly or detach in a crash, increasing the risk of injury.

Remedy:

Dealers will replace the driver's side impact air bag, free of charge. Owner notification letters are expected to be mailed December 1, 2023. Owners may contact Volkswagen's customer service at 1-800-893-5298. Volkswagen's number for this recall is 69FK.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

We have received Volkswagen's proposed owner notification letter, and it has been approved for distribution.

Please be reminded of the following requirements:



Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Volkswagen Group of America, Inc.'s contact for this recall will be Darishea Rollins who may be reached by email at darishea.rollins@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

