## News Channel Update

## Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Senior Manager, Vehicle
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services
RE: Recall Campaign Initial Notification	
Replace High-Pressure Fuel Pump	DATE: December 28, 2023
MY23-24 GLC and GLE (254 and 167)	

## IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above.

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Sincerely,

**Gregory Gunther** 

Senior Manager, Vehicle Compliance & Analysis



Recall Campaign Initial Notification		al Notification	December 28, 2023	
Campaign No.:	NHTSA ID	Campaign Desc. :	Replace High-Pressure Fuel Pump	
TBA	23V878	23P2197660		
	cles. The recall camp	aign will be visible on the www.	e fuel pump on <u>Z</u> Model Year ("MY") 2023-2024 GLC and GLE (254 NHTSA.gov website and may generate questions from customers. NDING" on <u>December 28, 2023</u> .	
		Backgrou	ınd	
Issue		Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that in certain Model Year ("MY") 2023-2024 GLE (167 platform) and GLC (254 platform) vehicles with the M254 engine, the bolting of the high-pressure fuel pump might not meet current specifications. In this case, the seal formed between the high-pressure fuel pump and tandem oil pump might be impaired. Thus, fuel and oil might leak and potentially spill onto the roadway, increasing the risk of a crash for the following traffic. If fuel or oil comes into contact with hot components, a risk of fire cannot be ruled out.		
What We're Doing		MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will replace the high- pressure fuel pump on the potentially affected vehicles.		
Parts		Remedy is not available at	this time.	
		Vehicles Aff	ected	
Vehicle Model Year(s)		2023-2024		
Vehicle Model		GLC and GLE		
		Vehicle Popu	lations	
Total Recall Population		7		
Total Vehicles in Dealer		0		
notification until th	e vehicle has been	repaired. Once the remedy is	r lease any new vehicles in dealer inventory covered by this available, the vehicles will be flagged as "OPEN" and Work e the repair is complete, the vehicle may be sold or leased.	
			st not be retailed until repaired. As a matter of normal service which might be applicable to the vehicle(s).	
Additionally, give	n this notice, it is a	violation of Federal Law for o notification until the vehicle	ear rental companies to rent new vehicles covered by this has been repaired.	
		Next Steps/	Notes	
Customer Notification	Гimeline	Customer letters will be ma	ailed on or before February 16, 2024.	
AOMS/SOMS		AOMs – This recall may get your dealers ASAP.	nerate questions from your dealers. Please forward this notice to	
Rental Fleet Partners		representative for further in preferred MBUSA dealer.	cles in your fleet. Please contact your respective MBUSA fleet information and next steps. For repairs, please contact your	
Customer Reimbursem	ent	Customer reimbursement i	s not being offered for this campaign.	
			o maintain a high level of vehicle quality and customer satisfaction. ssistance Center at 1-800-FOR-MERCEDES.	

