Next Unread Message

View Message

Sent on	02 09 2024 Expires on 05 08 2024
From	Motorcycle Sales National
Subject	STOP SALE NOTICE: 2017-2020 CBR600RR/RA SAFETY RECALL

Honda is issuing a **STOP SALE NOTICE on CERTAIN 2017-2020 CBR600RR/RA** motorcycles to **replace** the fuel pump assembly. Due to a manufacturing defect, the rubber impeller inside the fuel pump can warp or swell when exposed to fuel, causing the impeller to lock in place and prevent fuel flow to the engine. A locked impeller can cause the engine to stall without warning while riding.

Effective immediately, you **MUST NOT SELL any affected NEW or USED 2017-2020 CBR600RR/RA** motorcycle until it is inspected and repaired according to the associated Service Bulletin.

CBR600RR/RA #1, which includes all the information relating to this Safety Recall, is expected to be issued by the end of business **Friday**, **February 22**, **2024**, and can be found on iN by navigating to Service > Service Publications > Service Bulletins. Click <u>here</u> to view the Stop Sale letter.