OMB Control No.: 2127-0004

Part 573 Safety Recall Report

17V-280

Manufacturer Name: Volkswagen Group of America, Inc.

Submission Date: APR 26, 2017 NHTSA Recall No.: 17V-280 Manufacturer Recall No.: 51F5



Manufacturer Information:

Manufacturer Name: Volkswagen Group of America, Inc.

Address: 3800 Hamlin Road

Auburn Hills MI 48326

Company phone: 1-800-893-5298

Population:

Number of potentially involved : 2,091 Estimated percentage with defect : $100\,\%$

Vehicle Information:

Vehicle 1: 2015-2015 Audi A3 1.8T FWD S tronic

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: A3 1.8T FWD S tronic

Vehicle count: 991

Production Dates: NOV 28, 2013 - JAN 28, 2014

VIN Range 1: Begin: WAUCCGFF0F1000668 End: WAUACGFF2F1003997 ✓ Not sequential

Vehicle 2: 2015-2015 Audi A3 2.0T quattro S tronic

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: A3 2.0T quattro S tronic

Vehicle count: 1100

Production Dates: NOV 28, 2013 - JAN 28, 2014

VIN Range 1: Begin: WAUBFGFF5F1000653 End: WAUBFGFF9F1003992 ✓ Not sequential

Description of Noncompliance:

Description of the The safety certification label has an incorrect vehicle production date printed

Noncompliance: on it. This makes the label non-compliant with 49 CFR Part 567 – Certification,

specifically $\S567.4(g)(2)$ – "Month and year of manufacture: This shall be the time during which work was completed at the place of main assembly of the vehicle. It may be spelled out, as "June 2000", or expressed in numerals, as

"06/00".

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The label is non-compliant with 49 CFR Part 567 – Certification, specifically

\$567.4(g)(2) – "Month and year of manufacture: This shall be the time during which work was completed at the place of main assembly of the vehicle. It may be spelled out, as "June 2000", or expressed in numerals, as "06/00".

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: Audi AG

Address: N43-Ingolstadt/B318

Ingolstadt FOREIGN STATES 85051

Country: Germany

Chronology:

The matter was reviewed at an Audi Product Safety committee meeting during the first quarter of CY 2017. On April 19, 2017 the Audi Product Safety committee made the defect determination.

Description of Remedy:

Description of Remedy Program: Install an overlay label containing the correct vehicle production date. This

work will be free of charge to customers. No reimbursement will be

offered under this recall.

How Remedy Component Differs Overlay label will have a corrected vehicle production date.

from Recalled Component:

Identify How/When Recall Condition NR was Corrected in Production :

Recall Schedule:

Description of Recall Schedule: Dealer: Anticipated June 2017

Customers: Anticipated June 2017

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

^{*} NR - Not Reported