News Channel Update |

Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers	, FROM: Gregory Gunther, Senior Manager, Vehicle	
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
RE: Service Campaign Launch Notification		
Place Trickle Charger in Trunk	DATE: October 20, 2023	
MY22 SL (232 platform)		

IMPORTANT SERVICE CAMPAIGN LAUNCH

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES (1-800-367-6372).

Sincerely,

Gregory Gunther

Senior Manager, Vehicle Compliance & Analysis



Vehicle Compliance & Analysis

Service Campaign Launch Notification			October 20, 2023		
Campaign No. :	Campaign Desc. :	Place Trickle Charger in Trunk			
2023050003	23P5490205	ľ	lace Hickie Charger III Hulik		
	·	•	larger in the trunk in <u>3,582</u> Model Year ("MY") 2022 SL ed in VMI as "OPEN" on October 20, 2023.		
		Background			
Issue	determi operation the follow Vehicle	ined that on certair onal time of greater owing battery fault See Operator's M	AG"), the manufacturer of Mercedes-Benz vehicles, has a MY 2022 SL (232 platform) vehicles, after a longer non- rethan 42 days or with a battery charge of less than 45%, message might display in the instrument cluster: "Stop anual, Switch on vehicle to charge the 12V battery", or e12 V battery do not switch off vehicle."		
What We're Doing		JSA will conduct a service campaign. As a customer convenience measure, an norized Mercedes-Benz dealer will place a trickle charger in the vehicle's trunk.			
Parts	The rer	nedy is available a	and can be performed as necessary.		
	V	ehicles Affect	ed		
Vehicle Model Year(s) 2022					
Vehicle Model	nicle Model SL				
Vehicle Populations					
Total Campaign Population	Total Campaign Population 3,582				
Next Steps/Notes					
AOMS/SOMS	AOMs -	AOMs – This campaign may generate questions from your dealers.			
			to maintain a high level of vehicle quality and customer Assistance Center at 1-800-FOR-MERCEDES.		



Service Campaign Bulletin

Service Campaign Bulleti

Service Campaign Bulletin



Campaign No. 2023050003, October 2023

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model SL (232 platform)

Model Year 2022

Place Trickle Charger in Trunk

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2022 SL (232 platform) vehicles, after a longer non-operational time of greater than 42 days or with a battery charge of less than 45%, the following battery fault message might display in the instrument cluster: "Stop Vehicle See Operator's Manual, Switch on vehicle to charge the 12V battery", or "Stop vehicle To charge the 12 V battery do not switch off vehicle." As a customer convenience measure, an authorized Mercedes-Benz dealer will place a trickle charger in the vehicle's trunk.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 3,582 vehicles are affected.

Order No. P-SC-2023050003

Place Trickle Charger in Trunk

Work Procedure

1. Place trickle charger in truck.

Primary Parts Information

Qty.	Part Name	Part Number
1	Trickle charger	A0009822921

iNote: The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Damage Code	Operation Number	Description	Labor Time (hrs.)	
54 902 05	12-1875	Place trickle charger in vehicle	0.1	

Note: Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.