From: Broadcast Messaging System
To: <u>DL-BMS Message Monitors</u>

Subject: Parts Matrix

**Date:** Monday, December 19, 2016 3:42:13 PM

Publish Date: December 19, 2016
From: Parts Logistics
Expiration Date: January 02, 2017

DCSnet Message Reference



Subject: Parts Matrix

To: All BMW Parts and Service Managers

Re: Parts Matrix

Dear Parts and Service Managers,

Attached is the weekly Parts Matrix which includes the Highest Priority parts situation along with the ordering process. As a reminder, the Parts Matrix is updated weekly. It is important to monitor our daily DCS messages as things may change during the week.

As a reminder, regarding Thermostat Part Number 11 53 8 635 689, this part number remains on a daily maximum ordering quantity of 10 per day. We recommend ordering up to 10 per day only if you need them. Any orders placed over 10 pcs per day will be cancelled.

### Changes to this week's Parts Matrix are as follows:

- 1. Added Rear Side Window SIB51 48 16
- 2. Added Air Bag Module 16V-XXX SIB72 01 16
- 3. Added Air Bag Module 16V-XXX SIB72 02 16

## Air Bag Ordering: Please review the Vehicle Comments under each VIN before submitting an IDS ticket.

 As a reminder some air bags are being shipped to you for your used car inventory. Please check the VIN's listed in the PO with your Pre-Owned Sales Team. Please ensure that the Pre-Owned Inventory System (POIS) accurately reflects your current inventory.

## 1. Driver Air Bag 15V-318 (SIB 65 11 15):

 Parts are in Fair Share Allocation (FSA). Please remember to check the weekly allotment to help schedule your appointments. The quantities might change from week to week.

## 2. Driver Air Bag 16V-071:

- a. Please check the Vehicle Comments and if they indicate "Remedy is available" then order as needed via IDS ticket.
- Our parts distribution strategy follows the NHSTA requirements to prioritize parts for vehicles in the High Absolute Humidity (HAH) states and for oldest model years first. Additional letters will be mailed this week to customers, matching the parts availability.
- c. The new part numbers listed on EPC for accident cars and regular service repairs are active for ordering. These parts are open for normal ordering, please do not send an IDS ticket for an accident car.
- d. The Interim parts on your shelf listed in the current SIB's were the older parts from EPC.

<u>Vehicles</u>	<u>Interim</u>	<u>Updated SIB</u>
E83	32 30 6 884 326	32 30 6 884 311
	32 30 6 884 327	32 30 6 884 312
E8x and E90x	32 30 6 884 328	32 30 6 884 313
	32 30 6 884 329	32 30 6 884 314

E7x Inflator 32 30 6 884 812 32 30 6 884 813

Please continue to monitor our DCS messages and the weekly Matrix (attached) for parts ordering updates.

Thank you, Parts Logistics

Attachments:



Recipients: All, CC-All
All, All Offerings, All Regions, All Areas, Service, All
All, All Offerings, All Regions, All Areas, Parts, All

# PARTS MATRIX.

F15(X5), F25(X3), F26(X4)

(Driver)

F07(5), F10(5), F12(6), F13(6),

E70(X5), E71(X6), E72(X6H)

F1X (X5 X6), F2X (2 X3 X4), F3X (4)

F10 (5)

Air Bag

16V-683

**Fuel Pump** 

16V-746

**EPS** 

16V-704

Sensor

16V-832

Revision Date: December 19, 2016

If the VIN has Defect Code, please enter an

If the VIN has Defect Code, please enter an

**IDS Ticket order** 

**IDS Ticket order** 

Please do not send requests

Please do not send requests

All parts are available

No Stock

VIN's have defect code 0032440200

VIN's have defect code 0016150200

VIN's have defect code 0032450200

VIN's will have defect code 0065950200

No Stock (103 Vehicles)

Limited Stock (91 Vehicles)

65 22 16

16 04 16

32 10 16

65 28 16

PLEASE READ THE Q&A, THE SIB AND CHECK VEHICLE COMMENTS. Supply Criticality:

All letters were mailed for this recall

Limited supply in January

• Supply end of December

Full supply mid-December

Parts for	Vehicle(s)	SIB	Current Status	Forecast	Dealer Ordering Process
<b>Air Bag</b> 15V-318	E46(3), E39(5), E53(X5) (Driver)	65 11 15	<ul><li>Steady supply</li><li>VIN's have defect code 0032390200</li></ul>	All letters were mailed for this recall	Parts are in Fair Share Allocation
Inflator 16V-071	E70(X5), E71(X6), E72(X6H), E84(X1) (Driver)	65 14 16	<ul><li>Limited supply</li><li>VIN's have defect code 0032350200</li></ul>	Additional letters are being mailed monthly	<ul> <li>If Vehicle Comments is showing remedy available, please enter an IDS Ticket order</li> <li>Request complete airbag if needed per SIB</li> </ul>
Air Bag	E82(1), E88(1), E90(3), E91(3),		Limited supply		If Vehicle Comments is showing remedy

16V-071	(Driver)	65 14 16	VIN's have defect code 0032350200	Additional letters are being mailed monthly	<ul> <li>Request complete airbag if needed per SIB</li> </ul>
<b>Air Bag</b> 16V-071	E82(1), E88(1), E90(3), E91(3), E92(3), E93(3) (Driver)	65 16 16	<ul><li>Limited supply</li><li>VIN's have defect code 0032350200</li></ul>	Additional letters are being mailed monthly	If Vehicle Comments is showing remedy available, please enter an IDS Ticket order
<b>Air Bag</b> 16V-071	E83(X3) (Driver)	65 15 16	<ul><li>Limited supply</li><li>VIN's have defect code 0032350200</li></ul>	Additional letters are being mailed monthly	If Vehicle Comments is showing remedy available, please enter an IDS Ticket order

Air Bag E70(X5), E71(X6), E72(X6H), Very limited supply of interim part 65 19 16 • Third quarter of 2017. Please do not send requests VIN's have defect code 0072680100 16V-364 (Passenger)

# PARTS MATRIX.

Revision Date: December 19, 2016

Supply Criticality:

# PLEASE READ THE Q&A, THE SIB AND CHECK VEHICLE COMMENTS.

Vehicle(s) **Dealer Ordering Process** Parts for SIB **Current Status Forecast** Limited Stock (37 Vehicles) Repair instructions, Parts and Warranty information **Rear Side**  VIN's have comment STOP011934 B51 48 16 Please do not send requests F15(X5) 51 48 16 will be updated when available Window **Rear Side Window**  Approximately 2,080 vehicles affected Repair instructions, Parts and Warranty information Air Bag Module F06(6), F07(5), F10(5), F12(6), VIN's have Comment STOP011931 B72 01 16 Please do not send requests 72 01 16 F13(6), F33(4), F83(M4), F48(X1) will be updated when available 16V-XXX **Autoliv Air Bag Module** Approximately 177 vehicles affected Repair instructions, Parts and Warranty information Air Bag Module VIN's have Comment STOP811931 B72 02 16 72 02 16 Please do not send requests I01(i3), I12(i8) 16V-XXX will be updated when available **Autoliv Air Bag Module** Repair instructions, Parts and Warranty information DME F15(X5) 12 30 16 · Approximately 8 vehicles affected Please do not send requests will be updated when available 16V-XXX