

**OWNER REIMBURSEMENT PLAN**  
**Suzuki Motor of America, Inc.**

If your motorcycle is included in this recall and you have paid for repairs to address failure of the regulator/rectifier due to insufficient adhesion of the power module circuit board, you may be eligible for full or partial reimbursement. This reimbursement plan covers the following Suzuki motorcycles:

2008-2012 AN400 / AN400A produced from 8/1/2007 to 3/24/2012  
2008-2010 DL1000 produced from 7/27/2007 to 5/12/2010  
2012 DL1000 produced from 9/5/2011 to 2/28/2012  
2008-2009 GSF1250S / GSF1250SA produced from 7/17/2007 to 11/4/2008  
2008 GSX1300BK / GSX1300BKA produced from 7/18/2007 to 3/13/2008  
2008-2012 GSX1300R produced from 7/17/2007 to 3/15/2012  
2008-2010 GSX650F produced from 9/5/2007 to 2/24/2010  
2008-2010 GSX-R600 produced from 1/11/2008 to 9/17/2010  
2008-2010 GSX-R750 produced from 2/16/2008 to 8/31/2010  
2009-2010 SFV650 produced from 12/15/2008 to 5/13/2010  
2008-2010 VLR1800 / VLR1800T produced from 1/10/2008 to 1/15/2010  
2009-2010 VZ1500 produced from 7/9/2008 to 2/18/2010

Please note the following conditions for reimbursement:

- Only repairs made to address the defect that led to this recall are reimbursable. Additional expenses such as towing, car rental, accommodations, damage repairs, etc., will not be reimbursed. Reimbursement will not be provided for routine scheduled maintenance.
- Reimbursement may be limited to the suggested list price for parts, the Suzuki published flat rate time allowance for the repair, and the labor rate that an authorized Suzuki dealer in the same area would charge for the same repair.
- An owner will not be eligible for reimbursement if the expenses for repairs are incurred more than 10 days after the date of the last owner notification letter sent by Suzuki Motor of America, Inc.
- Reimbursement claims may also be excluded when adequate documentation is not submitted by the claimant. This includes a proof of ownership, a repair order, and proof of payment for the repair.

To request reimbursement for a previous repair, contact your Suzuki dealer.