

SSM 48899 - 2018-2020 F-150/F-Super Duty - Tailgate Step Assemblies - Step Binds/Will Not Open Or Opens/Pops Up While Driving

Some 2018-2020 F-150 and F-Super Duty vehicles equipped with tailgate step assemblies may exhibit a step assembly that binds/will not open or opens/pops up while driving. This could be due to an incorrect adjustment of the step assembly. Before replacing any components for this concern, follow the Tailgate Step Adjustment procedure in Workshop Manual, Section 501-04, General Procedures.

APPLICABLE VEHICLES

2018 - 2020 TRUCK: FC P552N F-150

2018 - 2020 TRUCK: FE P558N SUPER DUTY