

SSM 50461 - 2021-2022 Bronco - Soft Top Roof - Service Rivets Now Available

2021-2022 Bronco vehicles equipped with a factory soft top roof may require replacement of the soft top canopy material. Replacement rivets are now available (service part number W790580-S900). Each package contains 4 rivets.

APPLICABLE VEHICLES

2021 - 2022 TRUCK: G1 U725N BRONCO