SSM 50936

2022 Maverick - Bed Lighting Kit - Installation Instructions Updated

Some 2022 Maverick vehicles may exhibit an inoperative bed lighting kit (Lumen) or high mount lamps stay on after the installation. This may be due to discrepancies in the wiring connections in the installation sheet. For proper installation, use the updated online version of the installation sheet (B). Go to the Professional Technician System (PTS) web site, select Vehicle ID tab and enter the VIN. Select workshop tab, accessories, installation, installation sheet VNZ6Z-13E754-B Bed Lights By Lumen. For additional information, scan the QR code card shipped with this kit to display installation videos.