

NUMBER: 08-125-15

GROUP: Electrical

DATE: December 19, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 15-125. ALL APPLICABLE UN-SOLD RRT VIN'S HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE UN-SOLD VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. FOR VEHICLES NOT INCLUDED IN THE RRT VIN LIST, APPLICATION OF THIS SERVICE BULLETIN TO SOLD UNITS IS BASED UPON THE CUSTOMER EXPERIENCING THE SYMPTOM/CONDITIONS. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Premature Headlamp Bulb Failure

OVERVIEW:

This bulletin involves replacement of both headlamp bulbs.

MODELS:

2015 (LD) Dodge Charger

NOTE: This bulletin applies to vehicles built on or after July 01, 2015 (MDH 0701XX) and on or before September 15, 2015 (MDH 0915XX).

SYMPTOM/CONDITION:

The customer may experience premature headlamp failure.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. For all other customers that describe the symptom/condition listed above, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
2	L0009012LL	Headlamp Bulb

REPAIR PROCEDURE:

Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 08 Electrical> 8L - Lamps and Lighting> Lamps/Lighting - Exterior> Unit, Front Lamp> Removal and Installation> Bulb.

08-125-15 -2-

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-50-32-91	Headlamp Bulb, Replace Both Left And Right (0 - Low Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------